

FIG. 1






FIG.3





Sectional view cut on A-A

through hole 28






FIG.4


FIG.5






Sectional view cut on B-B


FIG.6






Sectional view cut on C-C

FIG.7





Sectional view cut on D-D

FIG.8




FIG.9

